


Announcement Product Discontinuation



Dear customer,

Hereby we would like to inform you about discontinuation of the following product:

SIL Relays with the pin layout "72"

Items affected:

SILxx-1A72-72L SILxx-1A72-72M
SILxx-1A72-72D SILxx-1B90-72L

Reason for Discontinuation:



Low customer demand and higher production costs don't benefit Standex-Meder to continue in manufacturing of the mentioned relays.

Discontinuation Date:

30. September 2015

Last Time Order Date:

30. August 2015

Standard Layout "71"	Discontinued Layout "72"
	

Replacement / Alternative Product:

There is not any replacement nor alternative product available regarding the pin layout . The electric parameters and functionality can be fully replaced by the standard SIL relays with the layout "71"

Support:

For technical questions or requests for future solutions, please contact Mr David Stastny

dstastny@standexmeder.com

David Stastny
Product Manager

Arndt Werlich
Chief Technology Officer

Ralf Maier
Chief Business Officer